

**Bill Arnold BMW Repair**

**Invoice 17604**  
Org. Est. # 033095

68 Woodland Ave Ste D  
San Rafael, California. 94901  
Phone: 415-459-2697 Fax: 415-457-2697

BAR# ARD 156510

**INVOICE**

Print Date: 11/09/2023 **Work Completed: 11/09/2023**

Darley, Mark

2001 BMW - M Coupe  
3.2L, In-Line6 (198CI) VIN(3), 5 speed Standard S5D310Z, 4  
Lic #: LTMTE30 - CA Odometer In : 99,389  
Unit # : Odometer Out :  
Vin # : WBSCN93401LK60019  
Hat # :

Home 415-310-5252  
Cust ID : 5679

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Extended
California battery fee. 25215.2(c) battery	1.00	2.00	2.00	Replace battery	0.25	50.00
battery 808	1.00	215.65	215.65	Washer system is not working Tank is full of algae. Remove, clean, and reinstall washer tank. Clean filter screen in mounting grommet.	0.75	150.00
Brake Pad Sensor-Rear 34 35 1 182 533	1.00	26.10	26.10	Check for drivetrain looseness	0.25	50.00
Brake Pad Set-Rear w/ Shims 34 21 1 162 536	1.00	132.85	132.85	Car has cumulative slack in the driveline between the crankshaft and rear wheels (flywheel, transmission, differential, and halfshafts)		
Brake Disc-Rear 34 21 2 227 177	1.00	239.81	239.81	Replace front brake pads, rotors, and sensor. Flush brake fluid	2.25	450.00
Brake Disc-Rear 34 21 2 227 178	1.00	239.81	239.81	Rear brakes are worn	2.00	400.00
Brake Fluid Brake Fluid	2.00	16.00	32.00	Replace rear brake pads, rotors, and sensor.		
Brake Pad Sensor-Front 34 35 2 227 385	1.00	26.10	26.10	Replace front control arms	3.50	700.00
Brake Pad Set-Front w/ Shims 34 11 1 162 535	1.00	169.86	169.86	Replace left front wheel bearing hub (with brakes removed)	0.50	100.00
Brake Disc-Front Left 34 11 2 227 171	1.00	247.68	247.68			
Brake Disc-Front Right 34 11 2 227 172	1.00	247.68	247.68			
Control Arm-Front Left Lower 31 12 2 228 461	1.00	317.30	317.30			
Control Arm-Front Right Lower 31 12 2 228 462	1.00	317.30	317.30			
Control Arm Bushing Kit-Front 31 12 9 069 035	1.00	63.77	63.77			
Axle Nut-Front 31 21 1 128 336	2.00	36.84	73.68			
Wheel Hub Assembly-Front Gen 2 31 22 6 757 024	1.00	298.43	298.43			

**Bill Arnold BMW Repair**

**Invoice 17604**  
Org. Est. # 033095

68 Woodland Ave Ste D  
San Rafael, California. 94901  
Phone: 415-459-2697 Fax: 415-457-2697

BAR# ARD 156510

**INVOICE**

Print Date: 11/09/2023 **Work Completed: 11/09/2023**

Darley, Mark

Home 415-310-5252  
Cust ID : 5679

2001 BMW - M Coupe  
3.2L, In-Line6 (198CI) VIN(3), 5 speed Standard S5D310Z, 4  
Lic # : LTMTE30 - CA Odometer In : 99,389  
Unit # : Odometer Out :  
Vin # : WBSCN93401LK60019  
Hat # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Extended
---------------------------	-----	------	-----	-------------------	-------	----------

[ Technicians : Arnold, Bill ]

Org. Estimate \$ 0.00 Revisions \$ 3,192.25 Current Estimate \$ 3,192.25

Revision # 1, Previous Estimate Amount: 0.00, Additional Cost: 1222.75, Revised Estimate: 1222.75, Parts: \$707.32 Labor: \$450.00 Sublet: \$0.00 Taxes & Fees: \$65.43 Authorized by - Darlev, Mark. Date - 11/7/2023. Time - 10:27 AM. Initiated By - Shop  
Revision # 2, Previous Estimate Amount: 2808.17, Additional Cost: 1462.97, Revised Estimate: 4271.14, Parts: \$698.37 Labor: \$700.00 Sublet: \$0.00 Taxes & Fees: \$64.60 Authorized by - Darlev, Mark. Date - 11/7/2023. Time - 1:31 PM. Initiated By - Shop  
Revision # 3, Previous Estimate Amount: 4271.14, Additional Cost: 506.53, Revised Estimate: 4777.67, Parts: \$372.11 Labor: \$100.00 Sublet: \$0.00 Taxes & Fees: \$34.42 Authorized by - Darlev, Mark. Date - 11/7/2023. Time - 3:05 PM. Initiated By - Shop

<b>Labor:</b>	<b>\$1,900.00</b>
<b>Parts:</b>	<b>\$2,650.02</b>
<b>Sublet:</b>	<b>\$0.00</b>
	-----
<b>Sub:</b>	<b>\$4,550.02</b>
<b>Tax:</b>	<b>\$245.13</b>
<b>Total:</b>	<b>\$4,795.15</b>
<b>Bal Due:</b>	<b>\$0.00</b>

[ Payments - American Express - \$4,795.15 ]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....